# PCI Token Ring Release Notes for HP-UX 10.20



Manufacturing Part Number: J1644-90022 E0301

U.S.A.

© Copyright 2001 © Hewlett-Packard Company.

## **Regulatory/Safety Statements**

## **FCC EMI Statement (USA Only)**

The Federal Communications Commission (in 47 CFR 15.19, 15.21 and 15.105) has specified that the following notices be brought to the attention of the users of this product.

This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residence is likely to cause harmful interference in which case the user will be required to correct the interference at his own expense.

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Cables used with this device must be properly shielded and grounded, terminating in either an RJ-45 or 9-pin D-shell connector. Any changes or modifications to this equipment not expressly approved by the Hewlett-Packard Company may cause harmful interference and void the FCC authorization to operate this equipment.

The end user of this product should be aware that any changes or modifications made to this equipment without the approval of Hewlett-Packard could result in the product not meeting the Class A limits, in which case the FCC could void the user's authority to operate the equipment.

## **Industry Canada EMI Statement**

This Class A digital apparatus meets all requirements of the Canadian Interference-Causing Equipment Regulations.

Cet appareil numerique de la classe A respecte toutes les exigences du Reglement sur le materiel brouilleur du Canada.

## **Europe EMI Statement**

This is a Class A product. In a domestic environment this product may cause radio interference in which case the user may be required to take adequate measures.

## **EMI (Australia and New Zealand)**

This product meets the applicable requirements of the Australia and New Zealand EMC Framework.



## **Safety Precautions**

WARNING

Before installing this product, refer to the installation instructions, including any safety precautions, for the Hewlett-Packard workstation product on which this product will be installed.

This product has two connectors, an RJ-45 and a 9-pin D-shell connector. It is important that the user connects to one or the other, but never to both at the same time. Refer to the *PCI Token Ring Adapter Quick Configuration Guide* (J1644-90024) for additional information.

## **Declaration of Conformity**

#### **DECLARATION OF CONFORMITY**

according to ISO/IEC Guide 22 and EN 45014

Manufacturer's Name: Hewlett-Packard Company

Manufacturer's Address: 8000 Foothills Blvd.

Roseville, CA 95747

USA

declares, that the product

Product Name: PCI Token Ring Network Interface Cards

Model Number(s): A4930-60001 (Product Number A4930A, 4/16 Mbps)

A5783-60001 (Product Number A5783A, 4/16/100 Mbps)

Product Options: All

conforms to the following Product Specifications:

Safety: IEC 950:1991 + A1, A2, A3, A4 / EN 60950:1992 + A1, A2, A3, A4

EMC: CISPR 22:1993 / EN 55022:1994 - Class A

EN 50082-1:1992, Generic Immunity, including:

IEC 801-2:1984, 8 kV AD IEC 801-3:1984, 3 V/m

IEC 801-4:1988, 1 kV Power Lines

0.5 kV Signal Lines

#### Supplementary Information:

The product herewith complies with the requirements of the EMC Directive 89/336/EEC and carries the CE marking accordingly.

Roseville, CA, March 3, 1999

Frank D. Dembski Jr., Quality Manager

Frank D. Dembolei for

European Contact: Your local Hewlett-Packard Sales and Service Office or Hewlett-Packard GmbH, Department TRE, Herrenberger Straße 130, D-71034 Böblingen (FAX: + 49-7031-14-3143)

## **Legal Notices**

The information in this document is subject to change without notice.

Hewlett-Packard makes no warranty of any kind with regard to this manual, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Hewlett-Packard shall not be held liable for errors contained herein or direct, indirect, special, incidental or consequential damages in connection with the furnishing, performance, or use of this material.

**Warranty.** A copy of the specific warranty terms applicable to your Hewlett- Packard product and replacement parts can be obtained from your local Sales and Service Office.

**Restricted Rights Legend.** Use, duplication or disclosure by the U.S. Government is subject to restrictions as set forth in subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS 252.227-7013 for DOD agencies, and subparagraphs (c) (1) and (c) (2) of the Commercial Computer Software Restricted Rights clause at FAR 52.227-19 for other agencies.

HEWLETT-PACKARD COMPANY 3000 Hanover Street Palo Alto, California 94304 U.S.A.

Use of this manual and flexible disk(s) or tape cartridge(s) supplied for this pack is restricted to this product only. Additional copies of the programs may be made for security and back-up purposes only. Resale of the programs in their present form or with alterations, is expressly prohibited.

Copyright Notices. ©copyright 1983-2001 Hewlett-Packard Company, all rights reserved.

Reproduction, adaptation, or translation of this document without prior written permission is prohibited, except as allowed under the copyright laws.

**Trademark Notices** UNIX is a registered trademark of The Open Group.

X Window System is a trademark of the Massachusetts Institute of Technology.

MS-DOS and Microsoft are U.S. registered trademarks of Microsoft Corporation.

OSF/Motif is a trademark of the Open Software Foundation, Inc. in the U.S. and other countries.

# **PCI Token Ring Release Notes**

This document applies to the latest release of the PCI Token Ring for HP-UX 10.20.

## What's In This Version?

## **Benefits and Features**

PCI Token Ring software (product number A5783A) supports 100/16/4 Mb/s hardware (part number A5783A) on all HP9000 workstations with the PCI bus.

The hardware is customer-installable on all PCI workstations. Refer to the hardware installation section in the *Installing and Administering Token Ring/9000* manual for detailed installation instructions.

## **Fixes**

Some fixes were incorporated into this release. See the section "Patches and Fixes in This Version" for more information.

## **Availability of Documentation**

The list below contains documentation related to PCI Token Ring.

- PCI Token Ring Quick Configuration Guide (J1644-90024).
- Installing and Administering Token Ring/9000 (J1644-90018).

These documents are also available at http://www.docs.hp.com under "Networking and Communications."

## **Known Problems and Workarounds**

- PHNE\_18173 (core LAN products patch) or any patch that supersedes it must be installed before the software product is installed. System panics can result if this patch is not installed prior to configuring PCI Token Ring.
- If the PCI Token Ring adapter is connected to a switch port or MAU and a mutually incompatible configuration is used, the driver and adapter may repeatedly try to connect into the network and fail. It is best to execute the shutdown script:

```
/sbin/rc1.d/K685pcitr stop, correct the problem then execute: /sbin/rc2.d/S315pcitr start.
```

This has the side effect of shutting down and restarting all PCI Token Ring links on the system.

The NetTL message logged for cable disconnect is different for 16/4 Mb/s and 100 Mb/s operation.

#### In 4/16 Mb/s, the message logged is:

```
"Cable disconnected/faulty" class ERROR #2009
```

## In 100 Mb/s, the message logged is:

```
"Internal error after beacon auto removal process" class ERROR #2010
```

In either case, when the cable is re-connected, the following message will be seen:

```
"Link back online" class INFO #4001
```

• A 100 Mb/s port on a switch will only support 100 Mb/s speed. A 16/4 Mb/s switch/MAU port will only support 16/4 Mb/s operation. Care should be taken while connecting the PCI Token Ring adapters to the network.

## **Compatibility Information and Installation Requirements**

## **Software Requirements**

The system must have standard HP-UX 10.20 core products, including STREAMS and LAN/9000 software, installed on it.

## **Hardware Requirements**

A5783A is supported on all HP 9000 workstations with the PCI bus.

## **OS Platform and Version Compatibility**

HP-UX CORE B.10.20.

## **Other Requirements**

PHNE\_18173 is required.

SAM patch PHCO\_21186 or any patch that supersedes it, is required for configuration through SAM.

## **Disc Space Required for Installation**

This product requires 700K bytes in addition to the current disc space being utilized.

## **Install/System Up or Down**

Software installation causes a system reboot.

## **Common Mistakes or Gotchas**

- Install PHNE\_18173 before installing the software product(s).
- Install PHCO\_21186 or any patch that supersedes it, before attempting SAM configuration.

## **Hardware Installation Instructions**

Refer to the *Installing and Administering Token Ring/9000* manual.

The following system classes are customer-installable:

- B-Class
- · C160 and higher
- J2240, J5000, J6000, and J7000

## **Software Installation Instructions**

Refer to the *Installing and Administering Token Ring/9000* manual.

After reboot, check the what (1) string on the kernel. Execute:

```
what /stand/vmunix | grep token
```

#### You should see:

A5783A/J1644AA HP PCI Token Ring <version> (<release>) <date>

#### where

<version> is B.10.20.01

<release> is DART 52

<date> is Dec 20 2000

## **Configuration Instructions**

Refer to the *Installing and Administering Token Ring/9000* manual.

## **Setting Speed and Duplexity**

Refer to the *Installing and Administering Token Ring/9000* manual.

## **Patches and Fixes in This Version**

The following are fixes in this version:

- lanscan(1M) now shows the MAC address of the PCI Token Ring card immediately after initialization, even if the cable is not connected.
- linkloop(1M) to itself, through a switch, will now work even if the card is in full duplex mode.
- The driver will now be able to transmit to multicast destinations without being a member of that multicast group.

# **Software Availability in Native Languages**

This product is available only in the English language.