

## Smart Array 5312 version 2.38

This Smart Array firmware will recommend updates for some SCSI disk drive models after the Smart Array firmware has been installed. To avoid notification during the POST routine, update any applicable hard disk drives before updating the Smart Array firmware.

Disk drive firmware components are available from:

[http://h18000.www1.hp.com/support/files/storage/us/locOsCat/99\\_56.html](http://h18000.www1.hp.com/support/files/storage/us/locOsCat/99_56.html)

If a component is not available for the affected disk drive model, download the following ROMPaq:

<http://h18000.www1.hp.com/support/files/server/us/download/17149.html>

A later version of the disk drive firmware may be available and should be used.

Disk Drive Model	Minimum Firmware	Disk Drive Family
AB009335B8	A019	SCSI 9GB 7200 WU
AB018335B9	A019	SCSI 18GB 7200 WU
AD009335C9	A018	SCSI 9GB 10K WU
AD018335CA	A018	SCSI 18GB 10K WU
AD018345A6	A009	SCSI 18GB 10K WU
BB009135B4	B021	SCSI 9GB 7200 WU2
BB009235B6	B021	SCSI 9GB 7200 WU2
BB018135B5	B021	SCSI 18GB 7200 WU2
BB018235B7	B021	SCSI 18GB 7200 WU2
BD009635C3	B022	SCSI 9GB 10K WU3
BD009735C6	B022	SCSI 9GB 10K WU3
BD018635C4	B022	SCSI 18GB 10K WU3
BD0186459A	B009	SCSI 18GB 10K WU3
BD018735C7	B022	SCSI 18GB 10K WU3
BD018745A3	B009	SCSI 18GB 10K WU3
BD036635C5	B022	SCSI 36GB 10K WU3
BD0366459B	B009	SCSI 36GB 10K WU3
BD036735C8	B022	SCSI 36GB 10K WU3
BD036745A4	B009	SCSI 36GB 10K WU3
BD0726459C	B009	SCSI 72GB 10K WU3
BF01865222	B007	SCSI 18GB 15K WU3
BF03665223	B007	SCSI 36GB 15K WU3
DGHS09U	01C0	SCSI 9GB 7200 WU
DGHS09Y	01C0	SCSI 9GB 7200 WU
DGHS18Y	01C0	SCSI 18GB 7200 WU
ST19171	9A10	SCSI 9GB 7200 WU