HP netserver PCI Slot and Cable Matrix

RILOE II may be server-slot specific. Determine an appropriate PCI slot by using the table below:

Table 1: Server PCI Slot and Cable Matrix

Server	PCI Slot	Remote Insight Internal Cable
LC 2000	1,2	2
tc3100	3,4,5,6	3
tc4100	3,4,5,6	4
LH 3000/3000r	7,8	1

NOTE: Virtual Power Button cables and Remote Insight internal cable description and part numbers include:
1 = P/N 303294-001 (4-pin cable assembly) ships with the RILOE II cable kit.
2 = P/N 303293-001 (4-pin cable assembly) ships with the RILOE II cable kit.
3 = P/N 303292-001 (4-pin cable assembly) ships with the RILOE II cable kit.
4 = P/N 303291-001 (4-pin cable assembly) ships with the RILOE II cable kit.

NOTE: All listed servers require the AC power adapter and keyboard/mouse adapter cable provided in the RILOE II kit.

NOTE: Disabling of the onboard video using the dip switch is not supported on these servers.

NOTE: The most current Server PCI Slot and Cable Matrix is available at

`www.hp.com/servers/lights-out`