

DR Tape Compatability Matrix for Windows NT 4.0 (Note: Service Pack 5 or higher must be installed)

Backup Application: Computer Associates Arcserve 2000

Compaq Server		ProLiant DL 360: Bios P21 or higher	ProLiant DL 380: Bios P17 or higher	ProLiant DL 580: Bios P20 or higher	ProLiant ML 350: Bios P02 or higher	ProLiant ML 370: Bios P17 or higher	ProLiant ML 530: Bios P19 or higher	ProLiant ML 570: Bios P20 or higher	ProLiant PL 1600: Bios P08 or higher	ProLiant PL 1850R: Bios P07 or higher	ProLiant PL 5500: Bios P12 or higher:	ProLiant PL 6400R: Bios P11 or higher	ProLiant PL 7000: Bios P40 / P43	ProLiant PL 8000: Bios P41 or higher	Tape Drive	Minimum Firmware Revision
Controller	Ultra 2 SCSI 64-bit 348757-B21	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	AIT 35GB	4.16
		4	4	4	4	4	4	4	4	4	4	4	4	4	AIT 50GB	1.31
		4	4	4	4	4	4	4	4	4	4	4	4	4	AIT 35GB LVD	3.09
		4	4	4	4	4	4	4	4	4	4	4	4	4	DAT 20/40GB	1.12
	Ultra Wide SCSI 3 Adapt 272514-001	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	AIT 35GB	4.16
		4	4	4	4	4	4	4	4	4	4	4	4	4	AIT 50GB	1.31
		4	4	4	4	4	4	4	4	4	4	4	4	4	AIT 35GB LVD	3.09
		4	4	4	4	4	4	4	4	4	4	4	4	4	DAT 20/40GB	1.12
	Symbios Embedded NOTE: The ROC module cannot be installed when using the DRTape Backup Solution	1	1	1	1	1	4	1	1	1	1	1	1	1	AIT 35GB	4.16
		1	1	1	1	1	4	1	1	1	1	1	1	1	AIT 50GB	1.31
		1	1	1	1	1	4	1	1	1	1	1	1	1	AIT 35GB LVD	3.09
		1	1	1	1	1	4	1	1	1	1	1	1	1	DAT 12/24GB	4.20
		1	1	1	1	1	4	1	1	1	1	1	1	1	DAT 20/40GB	1.12
		2	2	2	2	2	4	2	2	2	2	2	2	2	DAT 12/24GB AutoLoader	2.13
	Ultra 3 S/Channel HBA 154457-B21 Bios 3.02	2	2	2	2	2	4	2	2	2	2	2	2	2	DAT 20/40GB AutoLoader	5.06
		1	1	1	1	1	1	1	1	1	1	1	1	1	AIT 35GB	4.16
		1	1	1	1	1	1	1	1	1	1	1	1	1	AIT 50GB	1.31
		1	1	1	1	1	1	1	1	1	1	1	1	1	AIT 35GB LVD	3.09
		1	1	1	1	1	1	1	1	1	1	1	1	1	DAT 12/24GB	4.20
		1	1	1	1	1	1	1	1	1	1	1	1	1	DAT 20/40GB	1.12
		2	2	2	2	2	2	2	2	2	2	2	2	2	DAT 12/24GB AutoLoader	2.13
	2	2	2	2	2	2	2	2	2	2	2	2	2	DAT 20/40GB AutoLoader	5.06	
	1	1	1	1	1	1	1	1	1	1	1	1	1	1	SDLT	V-20
	Ultra 3 D/Channel HBA 129803-B21 Bios 3.02	1	1	1	1	1	1	1	1	1	1	1	1	1	AIT 35GB	4.16
		1	1	1	1	1	1	1	1	1	1	1	1	1	AIT 50GB	1.31
		1	1	1	1	1	1	1	1	1	1	1	1	1	AIT 35GB LVD	3.09
		1	1	1	1	1	1	1	1	1	1	1	1	1	DAT 12/24GB	4.20
		1	1	1	1	1	1	1	1	1	1	1	1	1	DAT 20/40GB	1.12
2		2	2	2	2	2	2	2	2	2	2	2	2	DAT 12/24GB AutoLoader	2.13	
2		2	2	2	2	2	2	2	2	2	2	2	2	DAT 20/40GB AutoLoader	5.06	
1	1	1	1	1	1	1	1	1	1	1	1	1	1	SDLT	V-20	

Supported Tape Drive Models (Internal and External)

- 1 - Requires SmartStart 4.9 or higher.
- 2 - Install SoftPaq # 14476 which corrects an AutoLoader Driver problem in SmartStart 4.9.
- 3 - Controller must be on the Primary PCI BUS.
- 4 - DRTape Backup Solution is not supported with this server, tape drive, controller and backup application configuration.