

---

## HP 64173A Compatibility Notice

You MUST review this notice to make sure your system's firmware and software are compatible if:

- You received an HP 64173A 4 Mbyte Static Random Access Memory (SRAM) module as a stand alone part of your order.
- You plan to move the HP 64173A 4 Mbyte SRAM module in this order to other HP 64700 series emulators.

If you received the HP 64173A 4 Mbyte SRAM module installed in an emulator and have no plans for moving it, you can ignore this notice.

The HP 64173A 4 Mbyte SRAM module is not compatible with older hardware, firmware, and software revisions. Check the following table to make sure your emulation system is compatible with the HP 64173A.

---

**HP 64173A Compatibility (versions must be those shown or newer)**

---

<b>Emulator</b>	<b>Hardware</b>	<b>Firmware</b>	<b>Software</b>
Motorola 68EC000	HP 64744 Emulator Board (64744-66512 or newer)	A.00.03 (26Apr93)	64742CNFG A.02.04 (31Mar92)
Motorola 68020	HP 64748D Emulator Probe	A.02.00 (29Jun93)	64748CNFG A.05.30 (14Apr94) and 64748EMUL A.02.00 (29Jun93) -or- 64748CNFG A.05.20 (02Jul93) and 64748EMUL A.02.01 (11Jan94)
Motorola 68030	HP 64747B Emulator Probe (64747-66508 or newer)	A.02.00 (09Jul93)	64747CNFG A.05.30 (14Apr94) and 64747EMUL A.02.00 (09Jul93) -or- 64747CNFG A.05.20 (08Jul93) and 64747EMUL A.02.01 (11Jan94)
Motorola 68040	HP 64783A Emulator Probe	Any version	64783CNFG A.05.30 (14Apr94) and 64783EMUL any version -or- 64783CNFG any version and 64783EMUL A.02.00 (14Apr94)
Motorola 68340	HP 64751A Emulator Probe (64751-66512 or newer)	A.00.11 (27Jul93)	64751CNFG any version
Motorola 68360	HP 64780A Emulator Probe	Any version	64780CNFG A.05.30 (14Apr94) and 64780EMUL any version -or- 64780CNFG any version and 64780EMUL A.00.20 (14Apr94)

Software version information can be found in the following directories:

/usr/hp64000/system (Sun host computer)

/system (HP 9000 host computer)

The 647xxEMUL filesets contain emulation firmware and are assumed to match the version of firmware loaded into the emulator. To check the version of the firmware loaded into the emulator, access the HP 64700's Terminal Interface and enter the "ver" command. (To access the Terminal Interface, you can use "pod\_command" in the Graphical User Interface or your computer's telnet command if the HP 64700 is on the Local Area Network.) If the versions do not match and the 647xxEMUL version is newer, use progflash(1) to update the emulator.

If you don't have the required software, firmware, or hardware, contact your HP Sales Representative or call the toll free Microprocessor Support Hotline, 1-800-447-3282.

