

Read Me Before Installing or Updating Pascal 3.2

HP 9000 Series 200 and 300 Computers



**HP Part No. 98617-90647
Printed in USA December 1991**

E1291

Warranty. The information contained in this document is subject to change without notice.

HEWLETT-PACKARD MAKES NO WARRANTY OF ANY KIND WITH REGARD TO THIS MATERIAL, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. Hewlett-Packard shall not be liable for errors contained herein or direct, indirect, special, incidental or consequential damages in connection with the furnishing, performance, or use of this material.

Hewlett-Packard assumes no responsibility for the use or reliability of its software on equipment that is not furnished by Hewlett-Packard.

A copy of the specific warranty terms applicable to your Hewlett-Packard product and replacement parts can be obtained from your local Sales and Service Office.

This document contains information which is protected by copyright. All rights are reserved. Reproduction, adaptation, or translation without prior written permission is prohibited, except as allowed under the copyright laws.

Restricted Rights Legend. Use, duplication or disclosure by the U.S. Government is subject to restrictions as set forth in paragraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS 252.227-7013 for DOD agencies, and subparagraphs (c) (1) and (c) (2) of the Commercial Computer Software Restricted Rights clause at FAR 52.227-19 for other agencies.

HEWLETT-PACKARD COMPANY
3000 Hanover Street
Palo Alto, California 94304 U.S.A.

Read Me Before Installing or Updating Pascal

Pascal 3.25

This release adds support for the Model 362 and 382 SPUs, including the built-in SCSI floppy drive (double-sided medium- and high-density disks only), the built-in SCSI hard disks, the VGA, the 1024x768 medium-resolution display, and the 1280x1024 high-resolution display.

Also supported is the 33 Mhz MC68040 385 SPU.

For installation instructions, refer to *Pascal 3.25 User's Guide*, HP Part Number 98615-90042.

New Hardware

- SPU Models 362, 362R, 382, 382R, and 385
- Internal Floppy Drive in the 362 and 382
- Built-in SCSI hard disks with the 362 and 382

Object Code Compatibility

Pascal 3.25 is generally upward code compatible with 3.2 systems. Note that this may not hold if the application contains linked in system modules.

Software Changes

- A new module CRTF has been created to support the VGA display available with the 362 and 382. This new module also supports the medium-resolution and high-resolution displays available with the 382. This module is present in the BOOT2: INITLIB file for double-sided floppy disks and in the BOOT3: INITLIB file for single-sided floppy disks.

- The DGL Library has been updated to support the new displays (VGA, medium-resolution, and high-resolution) available with the models 362 and 382.
- The SCSI driver has been enhanced to support the internal floppy drive built in to the models 362 and 382. The MEDIAINIT utility has been enhanced to support initialization of disks with the internal floppy disc drive (double-sided format options 0, 2, 3, and 16 only for medium- and high-density floppy disks).

System Discs

The following changes were made:

- Single-sided disks: Module CRTF was added to the INITLIB on the BOOT3: disk.
 TAPEBKUP.CODE was moved from the ACCESS: disk to the SYSVOL: disk.
- Double-sided disks: Modules SCSIDISC, SCSIDVR, and CRTF were added to the INITLIB file on the BOOT2: disk.
 EPROMS was moved from the ACCESS: disk to the SYSVOL: disk.

**** For HP Internal Reference Only ****

Customer Order Number

NONE

Printed in USA

Manufacturing Part Number

98617-90647

