

NATIVE TIMER
SYSTEM TEST ERROR MAP
PAGE 1 OF 1

MAP 37E0-1

001
(ENTRY POINT A)
THIS MAP SHOULD NOT BE ENTERED UNLESS AN
ERROR HAS OCCURRED WHILE EXECUTING
SYSTEM TEST, AND THEN ONLY WHEN THE
DEVICE TYPE FIELD IS EQUAL TO HEXADECIMAL
37
DOES THE FLAG FIELD = 8000 ?
N
002
DOES THE FLAG FIELD = 4000 ?
N
003
AN INTERRUPT WAS NOT RECEIVED (LOST
INTERRUPT).
GO TO STEP 005,
ENTRY POINT B.
004
AN ERROR WAS DETECTED ON THE CLASS
INTERRUPT.
GO TO STEP 005, ENTRY POINT B.
005
(ENTRY POINT B)
A MYSTERY INTERRUPT WAS RECEIVED.