

Release Note For Motorola Bluetooth Version 2.1.2.160

Notices

©2009 Motorola, Inc. 1303 East Algonquin Road Schaumburg, IL 60196 All rights reserved Printed in U. S. A.

Proprietary Material

Information and software in this document are proprietary to Motorola, Inc. and without the express prior permission of an officer of Motorola, Inc., may not be copied, reproduced, disclosed to others, published, or used, in whole or in part, for any purpose other than that for which it is being made available.

This document is for information purposes only and is subject to change without notice.

Information on the World Wide Web

Additional company and product information can be found on our Internet Web site at: http://www.motorola.com/pcsolutions

1 Product Release Identification

Date:April 03, 2009Product Name:Motorola BluetoothClassification:Production ReleaseVersion:2.1.2.160

The Motorola Bluetooth software is a powerhouse suite for Windowsbased personal computers. Users can connect wirelessly to their PC with a variety of Bluetooth devices, such as mobile phones, ear buds, stereo headsets, smart handhelds, printers, digital cameras and more.

2 Product Release Details

The current version of Bluetooth contains the following features/modifications:

- Release Components:
 - Product Installer ReadMe File
- > Target Platform:
 - o Windows XP
 - USB Cambridge Silicon Radio (BlueCore4)
- > Modifications/Updates:
 - ACSOL00015188 The progress bar of files transfer is different from the really progress.
 - ACSOL00015192 Bluetooth network will be disconnected while transferring large files
 - ACSOL00015300 The setting "Enable receiving files from other Bluetooth devices" doesn't work.
 - ACSOL00015401 BT stack shortcut is not generated in Desktop if install BT stack silent.

3 Product Specifications

- Bluetooth Core Interfaces:
 - Host Controller Interface (HCI) v2.1 + Extended Data Rate (EDR)
 - o Host Controller Interface (HCI) v2.0 + Extended Data Rate (EDR)
 - Host Controller Interface (HCI) v1.2
 - Host Controller Interface (HCI) v1.1
- Bluetooth Profiles:
 - o Advanced Audio Distribution Profile (A2DP) (Source)
 - o A/V Remote Control Profile (AVRCP) (Target)
 - o Dial-Up Networking Profile (DUN) (Data Terminal)
 - o Fax Profile (FAX) (Data Terminal)
 - File Transfer Profile (FTP) (Client/Server)
 - o Generic Access Profile (GAP)
 - Generic A/V Distribution Profile (GAVDP) (Source)
 - o Generic Object Exchange Profile (GOEP) (Client/Server)
 - o Hardcopy Replacement Profile (HCRP) (Host)
 - o Hands-Free Profile (HFP) (Headset, Audio Gateway)
 - o Headset Profile (HSP) (Headset, Audio Gateway)
 - o Human Interface Device Profile (HID) (Host)
 - Object Push Profile (OPP) (Client/Server)
 - o Personal Area Network Profile (PAN) (PAN-U Client)
 - o Service Discovery Application Profile (SDAP) (Client/Server)
 - Serial Port Profile (SPP) (Device A/B)
 - Synchronization Profile (SYNC) (Client)
 - o Basic Imaging Profile (BIP) (Push Responder)
 - Basic Printing Profile (BPP) (Sender)
- Bluetooth Protocols:
 - o Audio/Video Control Transport Protocol (AVCTP)
 - o Audio/Video Distribution Transport Protocol (AVDTP)
 - o Bluetooth Network Encapsulation Protocol (BNEP)
 - o Logical Link Control and Adaptation Protocol (L2CAP)
 - o Link Manager Protocol (LMP)
 - Object Exchange Protocol (OBEX)
 - o RF Communication (RFCOMM)
 - o Service Discover Protocol (SDP)
- ➤ Features:
 - o Intuitive Explorer User Interface
 - Bluetooth 2.1 and 2.0 SIG BQE Qualified and Listed
 - AT Command Handler (ATx)
 - Language: English, Traditional Chinese, Simplified Chinese, Japanese, French, Spanish, Brazilian Portuguese, German, Italian, Korean,

Russian, Swedish, Norwegian, Greek, Danish, Dutch, Finnish, Polish, Czech, Turkish.

4 Platform Requirements

- > Operating Systems:
 - o Windows Vista64
 - o Windows Vista
 - o Windows XP64
 - o Windows XP
- ➢ Bus Interfaces:
 - o USB 1.1
 - o USB 2.0
- Core Logic Chipsets
 - o Cambridge Silicon Radio BlueCore Chipset

5 Deliverables

[X] Release Note[X] Product

6 Field Support

> Please report all problems to Motorola Field Applications Engineers.

7 Release History

Release 2.1.2.160 (January 30, 2009)

- New Features Added:
 - o OEM Ready Release
 - Language support for Czech & Turkish
 - o Silent installer options updated.

Modifications/Updates:

- ACSOL00014756 [FTP] Error message after operating files with specific size
- ACSOL00014761 After disconnecting the link with the BT headset, the audio setting is still the "Bluetoot...
- o ACSOL00014778 Pop-up menu Japanese localization
- ACSOL00014779 Tray icon notification comes up when re-boot a system
- o ACSOL00014782 Localization of Telephony
- ACSOL00014823 Pop-up message for authorization through internet localization error
- ACSOL00014870 FTP & OPP services are unavailable
- o ACSOL00010403 Remove the authorization pop-up messages
- o ACSOL00014780 Dialog message comes up when access Internet
- o ACSOL00014898 [FTP] Can not copy empty file

Release 2.1.2.147 (December 18, 2008)

- New Features Added:
 - Localized Help Files and User Manuals for all supported languages
- Modifications/Updates:
 - o ACSOL00014309 A2DP usage in parallel with Mouse connection.
 - o ACSOL00014427 Dynamic Audio Plugin Implementation.
 - ACSOL00014275 Backing up and restoring progress bar are not filled up fully
 - ACSOL00014587 BSOD when MB stack performs A2DP- sink role under verifier
 - ACSOL00009739 Pairing/Unpairing didn't start for the first time after device discovery during DNAU
 - ACSOL00014541 Remove empty installation folders after uninstallation.
 - ACSOL00014667 Copying in the FTP folder with denied writepermission.

Release 2.1.2.141 (October 22, 2008)

- New Features Added:
 - o HFP Audio Gateway with BQE certification

- o SYNC Client with BQE certification
- BIP Push Responder with BQE certification
- o BPP Sender with BQE certification
- o Services are also available as links
- New logging capability added
- Add SetPoint mouse support
- Modifications/Updates:
 - o Readme update with license agreement
 - o Bluetooth SIG UPF 30 updates
 - Update receive file interface
 - o Wording updates
 - o Improve S3 wake up time

Release 2.1.1.128 (July 7, 2008)

- New Features Added:
 - Mass production support with license key verification on module
 - Add new languages: Swedish, Norwegian, Greek, Danish, Dutch, Finnish, Polish
- Modifications/Updates:
 - Readme update with license agreement
 - o Bluetooth SIG UPF 30 updates
 - Update receive file interface

Release 2.1.0.117 (May 23, 2008)

- ➢ New Features Added:
 - Improve PAN performance
 - Wording updates for FTP/OPP
 - o Improved Audio switching
 - o License Key Support
- Modifications/Updates:
 - o ACCSL00008353 Could not see the PAN service from MS inbox stack
 - o ACCSL00007535 Remove MS Bluetooth Icon

Release 2.1.0.117 (May 23, 2008)

- New Features Added:
 - Improve PAN performance
 - Wording updates for FTP/OPP
 - Improved Audio switching
 - License Key Support
- Modifications/Updates:
 - o ACCSL00008353 Could not see the PAN service from MS inbox stack
 - o ACCSL00007535 Remove MS Bluetooth Icon

Release 2.1.0.117 (May 23, 2008)

New Features Added:

- Improve PAN performance
- Wording updates for FTP/OPP
- Improved Audio switching
- o License Key Support
- Modifications/Updates:
 - ACCSL00008353 Could not see the PAN service from MS inbox stack
 - o ACCSL00007535 Remove MS Bluetooth Icon

Release 2.0.2.110 (April 25, 2008)

- New Features Added:
 - o Bluetooth Core 2.1 compliant
 - BQE Bluetooth 2.1 and all Profiles Certification
 - o Upgrade on user interface and make it more user friendly
 - Audio device switching support
 - o Add A2DP-Sink Profile support
 - Provide more info during FTP and OPP during transfer
 - o MUI language support compliant
- Modifications/Updates:
 - ACCSL00007692 [Qcom] Reduce power consumption
 - o ACCSL00007691 [Qcom] Improve PAN perfromance
 - o ACCSL00007535 [Qcom] Remove Microsoft Bluetooth Icon

Release 2.0.2.76 (December 29, 2007)

- New Features Added:
 - Update arrows on icons for received file settings
 - Add PAN profile to Windows Shell Explorer
- Modifications/Updates:
 - o ACCSL00007532 Update to interoperate with Microsoft Mouse
 - o ACCSL00007534 Update to interoperate with IVT PAN profile

Release 2.0.2.70 (December 12, 2007)

- New Features Added:
 - o Controlled Introduction Release